

SAFETY BULLETIN

No 10/026

Date Feb 11

Mapp Gas canister potential risk

Mapp Gas is used throughout the business. Following an investigation conducted by Norland Managed Services, it has been identified that a potential canister defect could result in the neck of the canister becoming unstable and weakening, resulting in an unsafe condition and unacceptable level of risk. Currently the ROTHENBERG type has been identified, however please adopt the actions detailed below for all Manufactures as a precaution.

Actions

The burner attachment for the canister must be disconnected while the equipment is not in use or before it is put back into storage &/or engineers vehicle



Regards

Kevin Gratton
HSQE Officer